

LABOR AND MATERIALS

1	Copper	Connection	\$
1	Lead	Connection	\$
1	Curb	Cock Valve T.S. & V.	in. \$
1	Service box	Short 3 1/2 x 4 1/2	\$
Old returned	Long 4 1/2 x 5 1/2	Buff or Rdway	
10	Ft. 3 in.	Copper Pipe at	\$
		G.I.	
		G.I.	
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g	Coupl'gs to in. at	\$
	Inc'g		
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints	at	\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man-1	at	\$
	Hrs. Water Maint. Man-2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins. at \$	per C	\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
	O'head		\$
			\$

*I done*

ARLINGTON St. Pl. Ave. No. 19

Name of Owner

Labor and Mat'l. Report *June 7* 19 *79*



8 Main Elev. of Main at tap 4' 2"

Gate at ● Gate at ●

● Curb Box