

13-1251

St. Aviation Rd.
Pl. _____
Ave. No. _____

Name of Owner
Charles Olmstead

Labor and Mat'l. Report Jan. 5 19 51



12" Main Elev. of Main at tap 4'
Gate at ● Gate at ●

● Curb Box

Tap on Butler main

LABOR AND MATERIALS

1	Copper Lead	{ Connection	<u>3/4"</u>	\$ <u>3.04</u>
1	Curb	{ Cock Valve T. S. & V. }	<u>3/4"</u> in.	\$ <u>3.54</u>
1	Service box Old returned	{ Short <u>3 1/2</u> x <u>4 1/2</u> Long <u>4 1/2</u> x <u>5 1/2</u> Buff or Rdway }		\$ <u>4.70</u>
15	Ft. <u>3/4"</u> in.	{ Copper G. I. C. I. }	Pipe at <u>35</u>	\$ <u>5.25</u>
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	{ Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints at			\$
	Compound Joints at			\$
2	Hrs. Water Maint. Man-1	at <u>1.23</u>		\$ <u>2.46</u>
	Hrs. Water Maint. Man-2	at		\$
2	Hrs. Labor	at <u>1.02</u>		\$ <u>2.04</u>
	Hrs. Labor	at		\$
	Hrs. Compressor at			\$
	Compensation Ins. at	\$ <u>2.66</u> per C.		\$ <u>1.72</u>
	Trucking			\$ <u>1.00</u>
	Pav't Patch	<u>outside</u>		\$
	O'head			\$
	Tap by Miller			\$ <u>22.15</u>
				<u>1-5-51</u>