

LABOR AND MATERIALS

1	Copper } Connection	3/4		\$ 1.35
	Lead			
1	Curb } Cock Valve	3/4	in.	\$ 1.80
	T. S. & V.			
1	Service Box } Short 3 1/4 x 4 1/4			\$ 1.70
	Old returned	Long 4 1/4 x 5 1/4		
		Buff for Rdway		
15 Ft.	3/4 in.	Copper Galv Iron	Pipe at	\$ 2.70
		Cap		
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g } Couplings	to in. at		\$
	Inc'g			
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$ 1.25
2	Hrs. Chauffeur	at	6 1/2 hr	\$ 1.25
2	Hrs. Tapper	at		\$
	Hrs. Labor	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$ 1.00
	Trucking			\$
	Builders Use of Water	at	city	\$
				\$
				\$
				\$
				\$
				\$ 11.13

New Raymond Weight
St.
Pl.
Ave. No.

Name of Owner *New Sheldon*
W. H. NOW STARK - 1989

Labor and Mat'l. Report *Sept 20* 19*41*

1st Yellow House
Above Charlotte Plant

Main Elev. of Main at tap

Gate at Gate at

● Curb Box