

LABOR AND MATERIALS

1	Copper	} Connection	<u>3/4</u>	\$	
	Lead				
1	Curb	} Cock Valve T.S. & V.	<u>3/4</u> in.	\$	
1	Service box		} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$
	Old returned				
20	Ft.	} Copper C.I. C.I.	<u>3/4</u> in.	Pipe at \$	
	Nipples			in. at \$	
	Bushings		to in. at \$		
	Red'g	} Coupl'gs			
	Inc'g			to in. at \$	
	Union		in. at \$		
	Meter		in. at \$		
	Lead Joints		at \$		
	Compound Joints		at \$		
	Maintenance Foreman		at \$		
	Hrs. Water Maint. Man		1 at \$		
	Hrs. Water Maint. Man		2 at \$		
	Hrs. Garage Foreman		at \$		
	Hrs. Labor		at \$		
	Hrs. Compressor		at \$		
	Compensation Ins.		at \$ per C		
	Trucking		\$		
	Pav't Patch		\$		
			\$		
			\$		
	O'head		\$		
			\$		

BALDWIN

St. 31
Pl. Ave. No. 31

Name of Owner
TAX ID # 302.12-16-4

Labor and Mat'l. Report

19

