

Labor and Materials

1	Copper } Connection 2"		\$ 19.65	
	Lead			
1	Curb } Cock Valve } 2" in.		\$ 15.30	
		T.S. & V.		
1	Service Box } Short 3 1/2 x 1 1/2	} Gate box 7.50	\$ 7.50	
	Old returned } Long 4 1/2 x 5 1/2			
		Buff. or Rdway		
33	Pt. 2" in.	Copper } Pipe at 64	\$ 27.72	
		Galv. Iron		
		Cast Iron		
	Nipples.....	in. at.....	\$	
	Bushings.....	to..... in. at.....	\$	
	Red'g } Couplings.....	to..... in. at.....	\$	
	Inc'g }			
	Union.....	in. at.....	\$	
	Meter.....	in. at.....	\$	
	Lbs. Br. Stone at.....		\$	
	Lbs. Sand at.....		\$	
	Bags Cement at.....		\$	
	Saving Brick } Mack	} at.....	\$	
				Red
				Asphalt
	Lead Joints at.....		\$	
	Leadite Joints at.....		\$	
11	Hrs. Foreman at.....	6 2/4	\$ 6.88	
27	Hrs. Common Labor at.....	40 5/8	\$ 10.97	
	Hrs. Common Labor at.....		\$	
	Hrs. Mason at.....		\$	
	Hrs. Mason's Helper at.....		\$	
	Hrs. Compressor at.....		\$	
	Compensation Ins.....		\$ 48	
	Trucking.....		\$ 1.00	
	Builders' Use of Water.....		\$	
Total			\$ 89.50	

238 Bay St. 28-102

Labor and Material Report Nov 16 1928

2' tap for to permit tapping
Buy it
No Measurement

● Curb Box

Main

Elev of Main at tap 4.4

Gate at ●

● Gate at

● Curb Box

1234

Three large scribbled-out circles.