

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	\$
	Lead			\$
1	Curb	} T. S. & V.	3/4 in.	\$
	Cock			\$
	Valve			\$
1	Service box	} { Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway }		\$
	Old returned		\$	
			\$	
11	Ft. 3/4 in.	} { Copper C. I. C. I. }	} Pipe at	\$
				\$
				\$
	Nipples	in. at		\$
1	Bushings	3/4 to 3/4	in. at	\$
	Red'g	} Coupl'gs	to in. at	\$
	Inc'g			
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
3	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
6	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins. at \$	per C.		\$
	Trucking			\$ 100
	Pav't Patch			\$
				\$
				\$
	O'head			\$
				\$ 1205

St. Pt. Ave. No. 36  
*Big Cross*

Name of Owner  
*Reardon*

Labor and Mat'l. Report *June 11* 19 *27*

20'9" 21'0"  
 ● Curb Box

4" Main Elev. of Main at tap 4'

Gate at ● Gate at ●

● Curb Box

*Card Flint*

L M-5C-2-1-54