

LABOR AND MATERIALS

1	Copper Lead	Connection	$\frac{3}{4}$	\$	1.79
1	Curb	Clock Valve T. S. & V.	$\frac{3}{4}$	in.	\$	2.61
1	Service box	Old returned	Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff or Rdway	}	Pipe at	1.82
14	Ft.	$\frac{3}{4}$ in.	Copper Galv. Iron Cast Iron	Pipe at	\$	3.22
	Nipples	in. at	\$	
	Bushings	to	in. at	\$	
	Red'g Inc'g	} Couplings	to	in. at	\$
	Union		in. at	\$
	Meter	in. at	\$	
	Lead Joints	at	\$	
	Compound Joints	at	\$	
1	Hrs. Foreman	at WWM	$9\frac{2}{2}$		\$	93
5	Hrs. Chauffeur	at	$8\frac{2}{2}$		\$	412
	Hrs. Tapper	at			\$	20
10	Hrs. Labor	at	$7\frac{1}{2}$		\$	7.15
	Hrs. Labor	at			\$	12
	Hrs. Compressor	at			\$	
	Compensation	Ins.			\$	1.34
	Trucking			\$	1
	Builders Use of Water				\$	5.00
	<i>Taphy Warsinski</i>				\$	
					\$	
					\$	
					\$	
					\$	
					\$	27.98

82-46

St. 16
Pl. 10
Ave. No. 10

Birch Ave

Name of Owner OConnell

Labor and Mat'l. Report Sept 9 1946

Elev. of Main at tap... 7

Gate at ● ● Gate at

TAX ID # 302.16-18-14

● Curb Box

LSM-5C-6-1-45