

LABOR AND MATERIALS

Copper _____ \$ _____
 Lead _____ \$ _____
 Curb } _____ in. _____ \$ _____
 _____ Service box { Short 3-1/2 x 4-1/2 } \$ _____
 Old returned { Long 4-1/2 x 5-1/2 }
 51.3' Ft. 3/4 in Pipe at _____ \$ _____
 _____ Nipples _____ in. at _____ \$ _____
 _____ Bushings _____ to _____ in. at _____ \$ _____
 _____ Red'g _____
 _____ Inc'g _____
 _____ Union _____ in. at _____ \$ _____
 _____ Meter _____ in. at _____ \$ _____
 _____ \$ _____
 _____ Compound Joints at _____
 _____ Maintenance Foreman _____
 _____ Hrs. Water Maint. Man - 1 at _____ \$ _____
 _____ Hrs. Water Maint. Man - 2 at _____ \$ _____
 _____ Hrs. Garage Foreman _____ at _____ \$ _____
 _____ Hrs. Labor _____ at _____ \$ _____
 _____ Hrs. Compressor at _____
 _____ Trucking _____
 _____ Pav't Patch _____

BOY N

St LOT
 Pl. Ave. No

of Owner
 TAX ID # 309.15-16-13

Labor and Mat'l 19

GARAGE

A

Curb Box

Elev. of Main at tap 4.75'

Gate at

Gate at

Curb Box

SEWER LATERAL C
 4" PVC ↓

D C = 11'-6"
 D = 21'-6"

E/P

BOYLSTON ST