

LABOR AND MATERIALS

Copper _____ \$
 Lead _____ \$
 Curb } n _____ \$
 _____ } _____ \$
17.9 t _____ \$
 Nipples _____ in. at _____ \$
 Bushings _____ to _____ in. at _____ \$
 Red'g _____
 Inc'g _____
 Union _____ in. at _____ \$
 Meter _____ in. at _____ \$
 Compound Joints at _____
 Maintenance Foreman _____
 Hrs. Water Maint. Man - 1 at _____
 Hrs. Water Maint. Man - 2 at _____
 Hrs. Garage Foreman _____ at _____ \$
 Hrs. Labor _____ at _____ \$
 Hrs. Compressor at _____
 Trucking _____
 Pav't Patch _____

Box N
 ST LOT
 Pl. Ave No 19
 Name
 TAX ID # 309.15-16-19

Labor and Mat'l. Report 19

A = 24'
 B = 37'-6" IN EASE
 A B
 Curb Box
 Elev. of Main at tap 5.75'
 8" Main
 Gate at Gate at

Curb Box
 C
 D
 E/P
 BOYLSTON ST