

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	\$	
	Lead				
1	Curb	} T.S. & V.	3/4 in.	\$	
1	Service box	} Short 3 1/2 x 4 1/2	}	\$	
	Old returned				Long 4 1/2 x 5 1/2
					Buff or Rdway
36	Ft.	} Copper	3/4 in.	Pipe at	
					G.I.
					C.I.
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	} Coupl'gs	to in. at	\$	
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints at			\$	
	Compound Joints at			\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man-1 at			\$	
	Hrs. Water Maint. Man-2 at			\$	
	Hrs. Garage Foreman at			\$	
	Hrs. Labor at			\$	
	Hrs. Compressor at			\$	
	Compensation Ins. at \$	per C		\$	
	Trucking			\$	
	Pav't Patch			\$	

Tap by Gifford
+ Co 7-1-59

O'head \$
36' Pipe furnished
by depart. Rest
furnished by owner
or builder. 5' from curb
box to tap.

St. Rd.
Pl. Ave. No. 35
Brooklakes

Name of Owner Searle

Labor and Mat'l. Report July 1 19 59

West side of house

50'

70' 2"

● Curb Box

Transite Queensbury Pl.
6" Main

Elev. of Main at tap 5 1/2'

Gate at ● Gate at ●

● Curb Box

This Tap on
Queensbury Pl.

Acres Pl.

LSM-5C-2-5-56