

LABOR AND MATERIALS

1	Copper Lead	Connection	1 1/4"	\$	7.77
1	Curb	Cock Valve T.S. & V.	1 1/4 in.	\$	2.18
1	Service box - Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$	6.22
45	Ft. 1 1/4 in.	Copper C.I. C.I.	Pipe at 62	\$	27.90
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Coupl'gs to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints at			\$	
	Compound Joints at			\$	
4	Maintenance Foreman		1.937	\$	7.75
	Hrs. Water Maint. Man-1 at			\$	
	Hrs. Water Maint. Man-2 at			\$	
	Hrs. Garage Foreman at			\$	
4	Hrs. Labor 2	at	1.481	\$	5.92
	Hrs. Compressor at			\$	
	Compensation Ins. at	\$ 5686 per C		\$.78
	Trucking			\$	1.50
	Pav't Patch	outside		\$	
	Tap by Muller & Posmer			\$	
			4-18-56	\$	
	O'head			\$	
				\$	66.62
				\$	22.40
				\$	43.62

St. Ph. Ave. No. _____

Broad Acres Rd. _____

Name of Owner Dr. Harvey

Labor and Mat'l. Report Apr. 18 19 56

#6 Ashley Pl. North Side

Broad Acres Rd.

12" Main Elev. of Main at tap 5'

Gate at • • Gate at

• Curb Box

This Tap Measured from #6 Ashley Pl. North Side.

M-5C-2-1-54