Labor and Materials

1	Copper / ~~Lead~~	Connection	$ 96
1	Curb	Cock / ~~Valve~~ / ~~T.S.&V.~~ ... in	$ 1.33
1	Service Box / Old returned	~~Short 3½x4½~~ / Long 4½x5½ / ~~Buff. or Rdway~~	$ 1.35
10	Ft. 3/4 in.	Copper / ~~Galv. Iron~~ / ~~Cast Iron~~ Pipe at 15	$ 1.50
	Nipples	in. at	$
	Bushings	to in. at	$
	Red'g / Inc'g	Couplings to in. at	$
	Union	in. at	$
	Meter	in. at	$
	Lbs. Br. Stone at		$
	Lbs. Sand at		$
	Bags Cement at		$
	Paving Brick	Mack / Red / Asphalt at	$
	Lead Joints at		$
	Leadite Joints at		$
	Hrs. Foreman at		$
	Hrs. Common Labor at		$
	Hrs. Common Labor at		$
	Hrs. Mason at		$
	Hrs. Masons Helper at		$
	Hrs. Compressor at		$
	Compensation Ins		$
	Trucking		$
	Builders Use of Water	Kopatch outside	$

Total $

33/36

Labor and Material Report Nov 27 1936

8 Broadacres Road Roadh Moynihan

6 Main

Elev. of Main at tap 5

Gate at ●

● Gate at

● Curb Box

New Tap.