

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	\$
	Lead			
1	Curb	} Cock Valve T. S. & V.	3/4 in.	\$
1	Service box	} { Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway }		\$
	Old returned			
12	Ft. 3/4 in.	} { Copper C. I. C. I. }	Pipe at	\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g } Inc'g }	Coupl'gs	to in. at	\$
		Union	in. at	\$
		Meter	in. at	\$
		Lead Joints	at	\$
		Compound Joints	at	\$
		Maintenance Foreman		\$
		Hrs. Water Maint. Man-1	at	\$
		Hrs. Water Maint. Man-2	at	\$
		Hrs. Garage Foreman	at	\$
		Hrs. Labor	at	\$
		Hrs. Compressor	at	\$
		Compensation Ins. at \$	per C	\$
		Trucking		\$
		Pav't Patch		\$
		Tap by Gifford		\$
		Co.		\$
		4-24-62.		\$
	O'head			\$

St. Pl. Ave. No. 91

Byrne

Name of Owner James Sullivan

Labor and Mat'l. Report April 24 1962.

35'2" 46'

Garage

● Curb Box

12" Main Elev. of Main at tap 7'

● Gate at ● Gate at

● Curb Box

LSM-5C-3-10-61