

LABOR AND MATERIALS

1	Copper	} Connection	<u>5/4</u> "		\$
	Lead				
1	Curb	Cock Valve T.S. & V.	<u>3/4</u> in.		\$
1	Service box	}	Short 3 1/2 x 4 1/2		
	Old returned		Long 4 1/2 x 5 1/2		
			Buff or Rdway		\$
31	Ft.	}	Copper	Pipe at	\$
	<u>3/4</u> in.		G. I.		
			G. I.		
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g	Coupl'gs. to in. at			\$
	Inc'g				
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Compound Joints	at			\$
	Maintenance Foreman				\$
	Hrs. Water Maint. Man-1	at			\$
	Hrs. Water Maint. Man-2	at			\$
	Hrs. Garage Foreman	at			\$
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins. at \$	per C			\$
	Trucking				\$
	Pav't Patch				\$
	Top by Gissard, Miller				\$
	+ Co. 6-11-57				\$
	O'head				\$

V
 St. _____
 Pl. _____
 Ave. No. 52

Byrne

Name of Owner Ernest Sullivan

Labor and Mat'l. Report June 11 1957

70' 8" 6' 5"

● Curb Box

12" Main
Elev. of Main at tap 7'

Gate at ●
● Gate at

● Curb Box

LSM-5C-2-5 56