

LABOR AND MATERIALS

1	Copper Lead	} Connection <sup>3/4"</sup>	\$
1	Curb		} Cock Valve T-S. & V. } <sup>3/4"</sup> in.
1	Service box Old returned	} Short <sup>3 1/2</sup> x <sup>4 1/2</sup> Long <sup>4 1/2</sup> x <sup>5 1/2</sup> }	
9	Ft. <sup>3 1/4</sup> in.		} Copper C.I. C.T. }
	Nipples	in. at \$	
	Bushings	to in. at \$	
	Red'g Inc'g	} Coupl'gs to in. at \$	
	Union		in. at \$
	Meter	in. at \$	
	Compound Joints	at \$	
	Maintenance Foreman	\$	
	Hrs. Water Maint. Man—1	at \$	
	Hrs. Water Maint. Man—2	at \$	
	Hrs. Garage Foreman	at \$	
	Hrs. Labor—	at \$	
	Hrs. Compressor	at \$	
	Trucking	\$	
	Pav't Patch	\$	
		\$	
		\$	
		\$	
		\$	

CAMERON ~~St.~~  
~~Pl.~~ Ave. No. 6  
Name of Owner  
TAX ID # 302.12-25-4

Labor and Mat'l. Report 19 37

