

### LABOR AND MATERIALS

1	Copper	{ Connection	3/4"	\$	2.29
	Lead				
1	Curb	{ Cock Valve	3/4 in.	\$	2.70
		{ F.S. & V.			
1	Service box	{ Short 3 1/2 x 4 1/2		\$	4.25
	Old returned	{ Long 4 1/2 x 5 1/2			
		{ Buff or Rdway			
9	Ft. 3/4 in.	{ Copper	Pipe at 35	\$	3.15
		{ G.I.			
		{ G.I.			
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	{ Coupl'gs to in. at		\$	
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
1 1/2	Hrs. Water Maint. Man-1	at 1.12		\$	1.68
3	Hrs. Water Maint. Man-2	at 1.02		\$	3.06
14	Hrs. Labor	at 91		\$	12.74
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins. at \$	per C.		\$	39
	Trucking			\$	1.-
	Pav't Patch			\$	
				\$	
				\$	
				\$	
	O'head			\$	
				\$	31.26

12-1950

Before Paving

St. Charlotte  
~~Pt.~~ Ave. No. 15

---

Name of Owner  
Moe M. Bittman

---

Labor and Mat'l. Report July 7 1950

● Curb Box

---

4 Main Elev. of Main at tap 5'

Gate at ● ● Gate at

---

● Curb Box

LSM-5C 10-21-49