

LABOR AND MATERIALS

1	Copper	} Connection <sup>3/4"</sup>	\$
	Lead		
1	Curb	} Cock Valve } 7/4 in.	\$
			T. S. & V.
1	Service box	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 }	\$
	Old returned		
24	Ft. <sup>3/4"</sup>	} Copper C.I. C.I. }	Pipe at \$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g		
	Inc'g	} Coupl'gs to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
			\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man-1	at	\$
	Hrs. Water Maint. Man-2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$

CHERRY

St. ~~Pt.~~  
Ave. No. 39

Name of Owner

Labor and Mat'l. Report

JULY 1930



31' 27' 11"

● Curb Box

12" Main

Elev. of Main at tap 4 1/2'

Gate at ●

● Gate at

● Curb Box