

LABOR AND MATERIALS

1	Copper Lead	} Connection	3/4		\$
1	Curb	} Clock Valve F. S. & V.	3/4	in.	\$
1	Service box Old returned	} Short 3 1/2 X 4 3/4 Long 4 1/2 X 5 3/4 Buff or Rdway			\$
24	Ft.	3/4 in.		} Copper Cast Iron Cast Iron	Pipe at \$
	Nipples	in.		at	\$
	Bushings	to		in.	at \$
	Red'g Inc'g	} Couplings	to	in.	at \$
	Union	in.		at	\$
	Meter	in.		at	\$
	Lead Joints	at			\$
	Compound Joints	at			\$
	Hrs. Foreman	at			\$
	Hrs. Chauffeur	at			\$
	Hrs. Tapper	at			\$
	Hrs. Labor	at			\$
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.				\$
	Trucking				\$ <u>1.00</u>
	Builders Use of Water				\$
	<i>Tap by Miller</i>				
					\$
					\$
					\$
					\$
					\$

St. _____
 Pl. _____
 Ave. No. 53

Name of Owner _____
Miller

Labor and Mat'l. Report Aug 23 1947

28'8"
23'7"
29'2"
● Curb Box

12" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

TAX ID # 303.17-2-14

● Curb Box

LSM-5C-6-1-45