

LABOR AND MATERIALS

1	Copper Lead	} Connection ^{3/4}		\$
1	Curb		} Cock Valve T.S. & V.	in.
1	Service box Old returned	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2		
25	Ft. ^{3/4} in.		} Copper C.I. C.I.	Pipe at
	Nipples	in. at		\$
1	Bushings	^{3/4} to ^{1/2} in.	at	\$
	Red'g Inc'g	} Coupl'gs	to in. at	\$
	Union		in. at	\$
	Meter	in. at	\$	
	Compound Joints	at	\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man-1	at	\$	
	Hrs. Water Maint. Man-2	at	\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor	at	\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	

St.
Pl.
Ave. No. 61

CHERRY

Name of Owner _____

Labor and Mat'l. Report SEPT 19 25

19'10" 32'0"

● Curb Box

4" Main Elev. of Main at tap 6'

Gate at ● ● Gate at

25' to main

● Curb Box