

LABOR AND MATERIALS

1 Copper } Connection <sup>3/4"</sup> \$ \_\_\_\_\_  
 Lead }  
 1 Curb } Cock } 3/4 in. \$ \_\_\_\_\_  
 } Valve }  
 } T.S. & V. }  
 1 Service box { Short 3 1/2 x 4 1/2 }  
 Old returned { Long 4 1/2 x 5 1/2 } \$ \_\_\_\_\_  
 } Buff or Rdway }  
 9 Ft. <sup>3/4</sup> in. { Copper } Pipe at \$ \_\_\_\_\_  
 } C.I. }  
 } C.I. }  
 Nipples \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Bushings \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Red'g }  
 Inc'g } Coupl'gs \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Union \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Meter \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Lead Joints at \$ \_\_\_\_\_  
 Compound Joints at \$ \_\_\_\_\_  
 Maintenance Foreman \$ \_\_\_\_\_  
 Hrs. Water Maint. Man—1 at \$ \_\_\_\_\_  
 Hrs. Water Maint. Man—2 at \$ \_\_\_\_\_  
 Hrs. Garage Foreman \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Labor— \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Compressor at \$ \_\_\_\_\_  
 Compensation Ins. at \$ \_\_\_\_\_ per C \$ \_\_\_\_\_  
 Trucking \$ \_\_\_\_\_  
 Pav't Patch \$ \_\_\_\_\_  
 Tap by Gifford & Co \$ \_\_\_\_\_  
 July 18 1958 \$ \_\_\_\_\_  
 O'head <sup>at time of</sup> \$ \_\_\_\_\_  
 Change over from \$ \_\_\_\_\_  
 4" main to 6"

Mrs. Leabel C. Bauman  
 ✓  
 St. \_\_\_\_\_  
 -Pl- \_\_\_\_\_  
 Ave. No. 70  
 Name of Owner \_\_\_\_\_  
 Bauman  
 Labor and Mat'l. Report July 18 1958  
 #70  
 Cherry St.  
 14' 10"  
 18'  
 Curb Box  
 Auburn Pl.  
 6" Main Elev. of Main at tap 5'  
 Gate at • Gate at •  
 • Curb Box  
 Tap on Auburn Pl.