

## LABOR AND MATERIALS

1	Copper <del>Lead</del>	Connection	3/4		\$ 2.80	
1	Curb	Clock Valve T.S. & V.	3/4	in.	\$ 3.60	
1	Service box Old returned	Short 3 1/2 X 4 1/2 Long 4 1/2 X 5 1/2 Buff or Rdway			\$ 5.80	
8	Ft.	3/4 in.	Copper Galv Iron <del>Cast Iron</del>	Pipe at 35	\$ 280	
	Nipples	in.	at		\$	
	Bushings	to	in.	at	\$	
	Red'g Inc'g	Couplings	to	in.	at	\$
	Union	in.	at		\$	
	Meter	in.	at		\$	
	Lead Joints	at			\$	
	Compound Joints	at			\$	
	Hrs. Foreman	at			\$	
	Hrs. Chauffeur	at			\$	
	Hrs. Tapper	at			\$	
	Hrs. Labor	at			\$	
	Hrs. Labor	at			\$	
	Hrs. Compressor	at			\$	
	Compensation Ins.				\$	
	Trucking				\$	
	Builders Use of Water				\$	
	<i>Tap by Miller</i>				\$	
					\$	
					\$	
					\$	
					\$	

155 J 47

St.  
Pl.  
Ave. No. 76

Cherry

---

Name of Owner

Majumdar

---

Labor and Mat'l. Report

Aug 16 19 47

---

4"

Main

Elev. of  
Main at tap 5 1/2

---

Gate at ● ● Gate at

---

TAX-ID # 303.13-16-2

---

● Curb Box

LSM-5C-6-1-45