

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$
1	Curb	Cock Valve	3/4" in.	\$
		T.S. & V.		
	Service box	Short	3 1/2 x 4 1/2	
	Old returned	Long	4 1/2 x 5 1/2	
23	Ft.	3/4" in.	Copper Pipe at	\$
			G.I.	
			G.I.	
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g			
	Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
				\$
	Compound Joints at			\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1 at			\$
	Hrs. Water Maint. Man-2 at			\$
	Hrs. Garage Foreman at			\$
	Hrs. Labor at			\$
	Hrs. Compressor at			\$
				\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$

CHERRY

St.
 Pl.
 Ave. No. 10

Name of Owner

Labor and Mat'l. Report

JULY 1931



17'10" 17'

● Curb Box

4" Main

Elev. of Main at tap 4 1/2'

Gate at ●

● Gate at

● Curb Box