

LABOR AND MATERIALS

1	Copper	{ Connection	3/4"		\$ 2.29
	Lead				
1	Curb	{ Cock Valve	3/4" in.		\$ 2.70
		F.S. & V.			
1	Service box	{ Short 3 1/2 x 4 1/2			
	Old returned	Long 4 1/2 x 5 1/2			
		Buff or Rdway			\$ 4.25
14	Ft. 3/4 in.	{ Copper	Pipe at 35		\$ 4.90
		G.I.			
		G.I.			
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g	{ Coupl'gs	to in. at		\$
	Inc'g				
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Compound Joints	at			\$
6	Hrs. Water Maint. Man-1	at 1.12			\$ 6.72
3	Hrs. Water Maint. Man-2	at 1.02			\$ 3.06
6	Hrs. Labor	at 91			\$ 5.46
	Hrs. Labor	at			\$
2	Hrs. Compressor	at 1.20			\$ 2.40
	Compensation Ins. at \$2.226 per C.				\$ 34
	Trucking				\$ 1.00
	Pav't Patch				\$ 20.70
	Tap by Miller				\$
					\$
					\$
	O'head				\$
					\$ 53.82

33.12

Renewal
215-215

St.
Pl: Chester
Ave. No. 26

Name of Owner Boud

Labor and Mat'l. Report Oct. 13 1950

#26

39' 5"

37' 4"

● Curb Box

10" Main Elev. of Main at tap 6'

Gate at ● ● Gate at

TAX ID # 302-16-11-44

● Curb Box