

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$ 2.76
1	Lead	Cock		
1	Curb	Valve	3/4 in.	\$ 3.49
		P. S. & V.		
1	Service box	Short 3/4 X 4 1/2		
	Old returned	Long 4 1/2 X 5 1/2		
		Buff or Rdway		\$ 4.74
12	Ft.	Copper	38	\$ 4.56
	3/4 in.	G. I.		
		C. I.		
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g			\$
	Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Hrs. Water Maint. Man-1	at		\$
3	Hrs. Water Maint. Man-2	at 1.24		\$ 3.72
12	Hrs. Labor	at 1.13		\$ 13.56
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	at \$4.06 per C.		\$ 76
	Trucking			\$ 1.00
	Pay't Patch			\$ 8.10
	Tap made	Nov 6-53		\$
	by	Gifford		\$
	O'head			\$
				\$ 42.69

96-53

Chester St. Pt. Ave. No. 37

Name of Owner
Geo Spaulding

Labor and Mat'l. Report Nov 6 1953

10" Main Elev. of Main at tap 5'

Gate at ● Gate at ●

TAX ID # 302.16-12-35

● Curb Box

LSM-5C B 15-48