

## Labor and Materials

Copper	}	Connection.....			\$
Lead					
Curb	}	Cock	}	in	\$
		Valve			
		T. S. & V.			
Service Box	}	Short 3½ x 4½	}	in	\$
Old returned		Long 4½ x 5½			
		Buff. or Rdway			
Ft. ....	}	Copper	}	Pipe at	\$
in.		Galv Iron			
		Cast Iron			
Nipples		in. at			\$
Bushings		to		in. at	\$
Red'g	}	Conplings.....	to	in. at	\$
Inc'g					
Union		in. at			\$
Meter		in. at			\$
Lead Joints at					\$
Leadite Joints at					\$
Hrs. Foreman at					\$
Hrs. Chauffeur at					\$
Hrs. Tapper at					\$
Hrs. Labor at					\$
Hrs. Labor at					\$
Hrs. Compressor at					\$
Compensation Ins.					\$
Trucking					\$
Builders Use of Water					\$
					\$
					\$
					\$
					\$
					\$
					\$

St. \_\_\_\_\_  
 Pt. \_\_\_\_\_  
 Ave. No. 7

---

Name of Owner  
ST Mary School

---

Labor and Mat'l. Report Sept 16 1937

---

---

Elev. of Main at tap 4"

---

Gate at ● ● Gate at

---

● Curb Box

Shut off at Main  
1 hrs. Building Razed  
July 16 46

Tap installed 10/2/13.