

Labor and Materials

1	Copper } Connection ^{3/4}	\$ 1.25
1	Lead }
1	Curb { Cock Valve T.S.&V. } ^{3/4} in	\$ 1.70
1	Service Box { Short 3 1/2 x 4 1/2 }
	Old returned { Long 4 1/2 x 5 1/2 }	\$ 1.37
	Buff. or Rdway }
46 Ft.	46 Ft. in. { Copper Galv. Iron Cast Iron } Pipe at 13 1/2 x	\$ 6.71
	Nipples	in. at	\$
	Bushings	to	in. at \$
	Red'g } Couplings.....	to	in. at \$
	Inc'g }
	Union.....	in. at	\$
	Meter.....	in. at	\$
	Lbs. Br. Stone at	\$
	Lbs. Sand at	\$
	Bags Cement at	\$
	Paving Brick { Mack Red Asphalt } at	\$
	Lead Joints at	\$
	Leadite Joints at	\$
5	Hrs. Foreman at	6 2/3 x	\$ 3.13
4	Hrs. Common Labor at	50	\$ 2.-
36	Hrs. Common Labor at	45	\$ 16.20
	Hrs. Mason at	\$
	Hrs. Masons Helper at	\$
	Hrs. Compressor at	\$
	Compensation Ins	\$ 80
	Trucking	\$ 3.-
	Builders Use of Water Patch	\$ 5.00
Total			\$ 40.66

1935-156

Labor and Material Report

Oct 9

1935

3/4 tap at Church st



Main

Elev of Main at tap

Gate at ●

● Gate at

● Curb Box

Sheet off at Main
 Building razed
 July 16-46