COOLIDGE ~~St.~~ ~~Pl.~~ Ave. No. 22

Name of Owner

MALOY

Labor and Mat'l. Report 4-19 1937

29' 25' 9"

● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

OLD TAP SHUT OFF

LSM—5C—6-1-67

LABOR AND MATERIALS

1 Copper / ~~Lead~~ Connection 3/4 $

1 Curb { Cock / ~~Valve~~ / ~~T. S. & V.~~ } 3/4 in. $

1 Service box { Short 3½ x 4½ / ~~Long 4½ x 5½~~ } Old returned $

32 Ft. 3/4 in. { Copper / ~~G. I.~~ / ~~G. I.~~ } Pipe at $

Nipples in. at $

Bushings to in. at $

Red'g / Inc'g Coupl'gs to in. at $

Union in. at $

Meter in. at $

$

Compound Joints at $

Maintenance Foreman $

Hrs. Water Maint. Man—1 at $

Hrs. Water Maint. Man—2 at $

Hrs. Garage Foreman at $

Hrs. Labor— at $

Hrs. Compressor at $

$

Trucking $

Pav't Patch $

$

$

$

$

$