

LABOR AND MATERIALS

1	Copper	} Connection ^{3/4}	\$
	Lead		
1	Curb	} Cock Valve } ^{3/4} in.	\$
			T. S. & V.
1	Service box	} Short 3 1/2 x 4 1/2 }	\$
	Old returned		Long 4 1/2 x 5 1/2 }
11	Ft. ^{3/4} in.	} Copper C.I. } Pipe at	\$
			C.I.
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Inc'g }	Coupl'gs to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man-1	at	\$
	Hrs. Water Maint. Man-2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$

St. ~~St.~~
 Pt. ~~Pt.~~
 Ave. No. 25

COOLIDGE

Name of Owner
H. ELLSWORTH

Labor and Mat'l. Report 7-13 1937



4-26-2001
 CLEAN OUT
 NEXT TO H₂O

37' 24' 3"

● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

OLD SHUT OFF