

12/30 14:28

\\futuredec\newscans\SMender

U987

1.A

COOLIDGE St. Ave. No. 67

Name of Owner

Labor and Mat'l. Report DEC. 6 1926



42'3" 39'0"

● Curb Box

6" Main Elev. of Main at tap 4'

Gate at ● Gate at ●

● Curb Box

LSM-SC-6.1-67

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4	\$
1	Curb	Cock Valve T.S. & V.	3/4 in.	\$
1	Service box	Short 3 1/2 x 4 1/2		
	Old returned	Long 4 1/2 x 5 1/2		\$
45	Ft. 3/4 in.	Copper Pipe at		\$
		<del>C.I.</del>		
		<del>C.I.</del>		
	Nipples	in. at		\$
	Bushings	to in. at		\$
2	Red'g In'g	Coupl'gs 3/4	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
				\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor-	at		\$
	Hrs. Compressor	at		\$
				\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$