

LABOR AND MATERIALS

Copper	}	Connection			\$
Lead					
Curb	}	Cock Valve T. S. & V.			\$
Service Box	}	Short 3/2x4 1/2 Long 4 1/2x5 1/2 Buff. or Rdway			\$
Old returned					
Ft.	}	}			\$
	}	}			
Nipples					\$
Bushings					\$
Red'g Inc'g	}	Couplings			\$
Union					\$
Meter					\$
Lead Joints					\$
Leadite Joints					\$
Hrs. Foreman					\$
Hrs. Chauffeur					\$
Hrs. Tapper					\$
Hrs. Labor					\$
Hrs. Labor					\$
Hrs. Compressor					\$
Compensation Ins.					\$
Trucking					\$
Builders Use of Water					\$
					\$
					\$
					\$
					\$
					\$

St. **22-26**
 Pt.
 Ave. No. **16**

Cooper

Name of Owner _____

Measured
 Labor and Mat'l. Report **8/21/40** 19

old tap

● Curb Box

.....Main
Elev. of Main at tap.....

Gate at ●
● Gate at

● Curb Box

changed over from one Cooper St. tap to the one measured in here.