

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	\$
1	Lead			
1	Curb	} Cock Valve T.S. & V.	3/4 in.	\$
1	Service box	} Short 3 1/2 x 4 1/2	} 5' x 6"	\$
	Old returned			
			Buff or Rdway	\$
10	Ft.	} Copper	} Pipe at	\$
	3/4 in.			
		G.I.		\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g	} Coupl'gs	to in. at	\$
	Inc'g			
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man	—1 at		\$
	Hrs. Water Maint. Man	—2 at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	— at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	at \$ per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap by Barrett Co.			\$
				\$
				\$
	O'head			\$
				\$

St. Cooper
Pl. 12
Ave. No. 12

Name of Owner K. & J. Electrical Co

Labor and Mat'l. Report Nov. 3 1970

12

● Curb Box

H" Galv
Main

Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

LSM-SC-6-1-67

K&J Electrical