

LABOR AND MATERIALS

1	Copper	} Connection	3/4	\$	
	Lead				
1	Curb	} Cock	3/4 in.	\$	
				} Valve	
					T.S. & V.
1	Service box	} Short 3 1/2 x 4 1/2		\$	
	Old returned			Long 4 1/2 x 5 1/2	
27	Ft.	} Copper	3/4 in.	\$	
				} G.I.	
					G.I.
				Pipe at \$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	} Coupl'gs	to in. at	\$	
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
				\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man	1 at		\$	
	Hrs. Water Maint. Man	2 at		\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
				\$	
	Trucking			\$	
	Pav't Patch			\$	
				\$	
				\$	
				\$	
				\$	

COOPER

St. ~~PL~~
Ave. No. 67

Name of Owner

Labor and Mat'l. Report APR 3 1930



34'-3" 28'-6"

● Curb Box

4" Main Elev. of Main at tap 5'

Gate at ● Gate at

TAX ID # 303.13-19-12

● Curb Box

OLD TAP SHUT OFF
WATER MAIN IS UNDER
THE STORM MAIN