

LABOR AND MATERIALS

1	Copper	} Connection	3/4	\$	
	Lead				
1	Curb	} Cock Valve T.S. & V.	3/4 in.	\$	
1	Service box	} Short 3 1/2 x 4 1/2		\$	
	Old returned				Long 4 1/2 x 5 1/2
10	Ft. 3/4 in.	} Copper	} Pipe at	\$	
					G.I.
					G.I.
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	} Coupl'gs	to in. at	\$	
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
				\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man—1	at		\$	
	Hrs. Water Maint. Man—2	at		\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor—	at		\$	
	Hrs. Compressor	at		\$	
				\$	
	Trucking			\$	
	Pav't Patch			\$	
				\$	
				\$	
				\$	
				\$	
				\$	

St. COOPER
 Ave. No. 96
 Name of Owner TAX ID #303.13-9-6

Labor and Mat'l. Report JULY 8 1926



26 1/2" 29 1/2"

● Curb Box

4" Main
 Elev. of Main at tap 5'
 Gate at ● Gate at ●

● Curb Box

NEW TAP
 NEW HOUSE