

LABOR AND MATERIALS

1	Copper	} Connection	3/4	_____	\$ _____
	Lead				
1	Curb	} Cock Valve T.S.&V. }	3/4 in.	_____	\$ _____
1	Service box	} Short 3 1/2 x 4 1/2 }	_____	_____	\$ _____
	Old returned				
9	Ft.	} Copper G.I. C.I. }	3/4 in.	Pipe at _____	\$ _____
	Nipples	in. at _____			\$ _____
	Bushings	to _____ in. at _____			\$ _____
	Red'g } Inc'g }	Coupl'gs	to _____ in. at _____		\$ _____
	Union	in. at _____			\$ _____
	Meter	in. at _____			\$ _____
					\$ _____
	Compound Joints	at _____			\$ _____
	Maintenance Foreman	_____			\$ _____
	Hrs. Water Maint. Man-1	at _____			\$ _____
	Hrs. Water Maint. Man-2	at _____			\$ _____
	Hrs. Garage Foreman	at _____			\$ _____
	Hrs. Labor	at _____			\$ _____
	Hrs. Compressor	at _____			\$ _____
					\$ _____
	Trucking	_____			\$ _____
	Pay't Patch	_____			\$ _____
					\$ _____
					\$ _____
					\$ _____
					\$ _____

St. COOPER
~~PL~~
 Ave. No. 100

Name of Owner
 TAX ID # 303.13-9-8

Labor and Mat'l. Report AUG 22 1950



37'6" 36'6"

● Curb Box

4" Main

Elev. of Main at tap 5 1/2'

Gate at ●

● Gate at

● Curb Box

NEW HOUSE