

LABOR AND MATERIALS

1	Copper	} Connection	_____	\$ _____	
	Lead				
1	Curb	} Cock } Valve } T.S. & V.	_____ in.	\$ _____	
1	Service box		} Short 3 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2	_____	\$ _____
	Old returned				
31	Ft. 3/4 in.	} Copper } G.I. } G.I.	_____ Pipe at	\$ _____	
1	Nipples 2 in.		at	\$ _____	
1	Bushings 1" to 3/4 in.		at	\$ _____	
1	Reddg Ine'g	} Coupl'gs	_____ to _____ in.	at \$ _____	
	Union		_____ in.	at \$ _____	
	Meter	_____ in.	at \$ _____		
	Compound Joints	at \$ _____			
	Maintenance Foreman	\$ _____			
	Hrs. Water Maint. Man-1	at \$ _____			
	Hrs. Water Maint. Man-2	at \$ _____			
	Hrs. Garage Foreman	at \$ _____			
	Hrs. Labor	at \$ _____			
	Hrs. Compressor	at \$ _____			
	Trucking	\$ _____			
	Pav't Patch	\$ _____			
		\$ _____			
		\$ _____			
		\$ _____			
		\$ _____			
		\$ _____			

COOPER St. Pt. Ave. No. 107

Name of Owner
TAX ID # 303.13-4-13

Labor and Mat'l. Report JULY 12, 1928



● Curb Box

6" Main Elev. of Main at tap 5'
Gate at ● Gate at

● Curb Box