

**Labor and Materials**

1	Copper } Connection	1		\$ 3.20
	Lead } Valve			
1	Orb { Cock } P.S. & V.		in.	\$ 1.00
1	Service Box } Short 3 1/2 x 4 1/2 Old returned } Long 4 1/2 x 5 1/2 Buff. or Rdway }			\$ 1.30
20	Ft. in. } Copper Cast Iron } Pipe at	3/4		\$ 4.40
	Nipples		in. at.	\$
	Bushings		to..... in. at.	\$
	Red'g } Couplings		to..... in. at.	\$
	Inc'g }			
	Union		in. at.	\$
	Meter		in. at.	\$
	Lbs. Br. Stone		at.	\$
	Lbs. Sand		at.	\$
	Bags Cement		at.	\$
	Paving Brick { Mack Red } at		Asphalt }	\$
	Lead Joints		at.	\$
	Leadite Joints		at.	\$
	Hrs. Foreman		at.	\$
4	Hrs. Common Labor	50		\$ 2.00
8	Hrs. Common Labor	40 5/8		\$ 3.20
	Hrs. Mason		at.	\$
	Hrs. Mason's Helper		at.	\$
	Hrs. Compressor		at.	\$
	Compensation Ins.			\$ .14
	Trucking			\$ 1.00
	Builders' Use of Water			\$
<b>Total</b>				\$ 16.29

**Labor and Material Report**

Sept 19 1927

28 Cortland St



Main Elev. of Main at tap 4 1/2

Gate at 20' to main Gate at

Curb Box

tap new house