

Labor and Materials

Copper	}	Connection.....			\$
Lead					
Curb	{	Cock	}	in	\$
		Valve			
		T. S. & V.			
Service Box	}	Short 3½ x 4½	}		\$
Old returned		Long 4½ x 5½			
		Buff. or Rdway			
6 Ft. 3/4 in.		Copper	} Pipe at		\$
		Galv. Iron			
		Cast Iron			
Nipples		in. at			\$
Bushings		to	in. at		\$
Red's	}	Couplings.....	to	in. at	\$
Inc'g					
Union		in. at			\$
Meter		in. at			\$
Lead Joints		at			\$
Leadite Joints		at			\$
Hrs. Foreman		at			\$
Hrs. Chauffeur		at			\$
Hrs. Tapper		at			\$
Hrs. Labor		at			\$
Hrs. Labor		at			\$
Hrs. Compressor		at			\$
Compensation Ins.				\$
Trucking				\$
Builders Use of Water				\$
				\$
				\$
				\$
				\$
				\$
				\$

St. Crandall
 Pt. 14
 Ave. No. 14

Name of Owner
Mrs. Henry Dudley

Labor and Mat'l. Report TAP made
Sept 12 1921

6/11/1921
Main Cottage Elev. of Main at tap 5

Gate at • • Gate at

• Curb Box

21' 7" 24' 10"