

Labor and Materials

1	Lead Connection	\$
	Curb Cock	\$
1	Service Box	{ Short 3 $\frac{1}{2}$ x 4 $\frac{1}{2}$	\$
	Old returned	{ Long 4 $\frac{1}{2}$ x 5 $\frac{1}{2}$	
		{ Buffalo	
11	Ft. in. G. I. Pipe at	\$
	Nipples in. at	\$
	Bushings 1" to 1 $\frac{1}{2}$ " in. at	\$
	Red'g Coup to in. at	\$
	Inc'g Coup to in. at	\$
	Union in. at	\$
	Meter in. at	\$
	Cu. Yds. Br. Stone at	\$
	Cu. Yds. Sand at	\$
	Bags Cement at	\$
	Paving Brick	{ Mack	} at
		{ Red	
		{ Asphalt	
3	Hrs. Foreman at	\$
13	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs. at	\$
	Hrs. at	\$
200	Builders' Use of Water	\$
	 at	\$
	Truck 100 at	\$
	 at	\$
	 at	\$
	Total	\$ 151.02	

Labor and Material Report Oct 4 1924

Tap at 5 Crandall at



8" Main Elev. of Main at tap 4 ft

Gate at ● ● Gate at

● Curb Box

17' 0" 27' 10"