

LABOR AND MATERIALS

Copper	} Connection		\$	
Lead				
Curb	} T. S. & V. } in.		\$	
		Cock		
		Valve		
Service box	} Short 3½ x 4½ }			
Old returned		Long 4½ x 5½ }		\$
8? Ft. ¾" in.	} Copper } Pipe at		\$	
		C.I.P.		
Nipples	in. at		\$	
Bushings	to in. at		\$	
Red'g } Inc'g }	} Coupl'gs to in. at		\$	
Union		in. at		\$
Meter	in. at		\$	
			\$	
Compound Joints at			\$	
Maintenance Foreman			\$	
Hrs. Water Maint. Man—1 at			\$	
Hrs. Water Maint. Man—2 at			\$	
Hrs. Garage Foreman at			\$	
Hrs. Labor— at			\$	
Hrs. Compressor at			\$	
			\$	
Trucking			\$	
Pav't Patch			\$	
			\$	
			\$	
			\$	
			\$	

CRANDALL

St. Pt. Ave. No. 37

Name of Owner

Labor and Mat'l. Report

JULY 9 1985



● Curb Box

10" Main

Elev. of Main at tap 4'

Gate at ●

● Gate at

● Curb Box