Bill rendered

Labor and Materials

1	Copper / Lead } Connection 3/4	$ 320
1	Curb { Cock / Valve / T. S. & V. } 3/4 in.	$ 100
1	Service Box / Old returned { Short 3½ x 4½ / Long 4½ x 5½ / Buff. or Rdway }	$ 130
13	Ft. 3/4 in. { Copper / Galv. Iron / Cast Iron } Pipe at	$ 286
	Nipples ..... in. at	$
	Bushings ..... to ..... in. at	$
	Red'g / Inc'g } Couplings ..... to ..... in. at	$
	Union ..... in. at	$
	Meter ..... in. at	$
	Lbs. Br. Stone at	$
	Lbs. Sand at	$
	Bags Cement at	$
	Paving Brick { Mack / Red / Asphalt } at	$
	Lead Joints at	$
	Leadite Joints at	$
	Hrs. Foreman at	$
	Hrs. Common Labor at	$
	Hrs. Common Labor at	$
	Hrs. Mason af	$
	Hrs Mason's Helper at	$
	Hrs. Compressor at	$
	Compensation Ins.	$
	Trucking	$
	Builders' Use of Water	$
	Total	$

Labor and Material Report June 96 19

no 71 Crandell st

no measurement

Curb Box

10" Main

Elev. of Main at tap 5'

Gate at

Gate at

Curb Box

vacant lots

REAR OF 38 GROVE