

Labor and Materials

1	Lead Connection	3/4	\$
1	Curb Cock		\$
1	Service Box	{ Short 31 x 41	\$
	Old returned	{ Long 41 x 51	\$
15	Ft. 1 in. G. I. Pipe at	Buffalo	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Coup	to in. at	\$
	Inc'g Coup	to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Cu. Yds. Br. Stone at		\$
	Cu. Yds. Sand at		\$
	Bags Cement at		\$
	Paving Brick	{ Mack Red Asphalt } at	\$
3	Hrs. Foreman at		\$
13	Hrs. Common Labor at		\$
	Hrs. Mason at		\$
	Hrs.	at	\$
	Hrs.	at	\$
90	Builders' Use of Water		\$
	Truck	100	\$
		at	\$
		at	\$
		at	\$
	Total	\$15.73	

Labor and Material Report Oct 4 1924

3/4 tap at 9 Crandall at
Stub

Curb Box

8" Main Elev. of Main at tap 4

Gate at ● ● Gate at

Curb Box

3/4 tap at 9 Crandall

24' 4" 14' 0"

Stub at old
shut off