LABOR AND MATERIALS

1 Copper / ~~Lead~~ } Connection 3/4 ____ $____

1 Curb { Cock / ~~Valve~~ / ~~T. S. & V.~~ } 3/4 in. ____ $____

1 Service box { ~~Short 3½ x 4½~~ / Long 4½ x 5½ } Old returned ____ $____

25 Ft. 3/4 in. { Copper / ~~C.I.~~ / ~~C.I.~~ } Pipe at ____ $____

____ Nipples ____ in. at ____ $____

____ Bushings ____ to ____ in. at ____ $____

1 { ~~Red'g~~ / Ins'g } Coupl'gs 3/4 to ____ in. at ____ $____

____ Union ____ in. at ____ $____

____ Meter ____ in. at ____ $____

____ ____ $____

____ Compound Joints at ____ $____

____ Maintenance Foreman ____ $____

____ Hrs. Water Maint. Man—1 at ____ $____

____ Hrs. Water Maint. Man—2 at ____ $____

____ Hrs. Garage Foreman ____ at ____ $____

____ Hrs. Labor— ____ at ____ $____

____ Hrs. Compressor at ____ $____

____ $____

____ Trucking ____ $____

____ Pav't Patch ____ $____

____ $____

____ $____

____ $____

____ ____ $____

$____

St. ~~Pl.~~ ~~Ave.~~ No. 122

CRANDALL

Name of Owner

Labor and Mat'l. Report JUNE 23 1927

35'6" 33'6"

● Curb Box

10" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

OLD TAP SHUT OFF

LSM—5C—6-1-67