

LABOR AND MATERIALS

1	Copper Lead	} Connection	_____	\$
1	Curb		} Cock Valve T. S. & V. }	3 7 in.
1	Service box	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 }		
29	Old returned			
22	Ft. 3/4	} Copper Pipe	_____	\$
Kit				
	Nipples	_____ in. at _____	\$	
	Bushings	_____ to _____ in. at _____	\$	
	Red'g Inc'g	} Coupl'gs _____ to _____ in. at _____	\$	
	Union			_____ in. at _____
	Meter	_____ in. at _____	\$	
	Compound Joints	at _____	\$	
	Maintenance Foreman	_____	\$	
	Hrs. Water Maint. Man	—1 at _____	\$	
	Hrs. Water Maint. Man	—2 at _____	\$	
	Hrs. Garage Foreman	_____ at _____	\$	
	Hrs. Labor	_____ at _____	\$	
	Hrs. Compressor	at _____	\$	
	Trucking	_____	\$	
	Pav't Patch	_____	\$	
		_____	\$	
		_____	\$	
		_____	\$	
		_____	\$	

DARWIN

~~St. No.~~
~~St. No.~~
Ave. No. 3

Name of Owner _____

Labor and Mat'l. Report

APR. 20 1927



32-2 27-0

● Curb Box

4" Main

Elev. of Main at tap 4 1/2'

Gate at ●

● Gate at

● Curb Box

NEW HOUSE