

LABOR AND MATERIALS

1	Copper	} Connection <u>3/4</u>	\$
	Lead		
1	Curb	} <u>3/4</u> in.	\$
	Cock		
	Valve T. S. & V.		
1	Service box	} Short <u>3 1/2</u> x <u>4 1/2</u> Long <u>4 1/2</u> x <u>5 1/2</u>	\$
30'	Old returned		
<del>8</del>	Ft. <u>3/4</u> in.	} Copper C.I. C.I.	Pipe at \$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g	} Coupl'gs to in. at	\$
	Inc'g		
	Union	in. at	\$
	Meter	in. at	\$
			\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man-1	at	\$
	Hrs. Water Maint. Man-2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$

DARWIN

Ave. No. 11

Name of Owner

TAX ID # 309.7-9-3

Labor and Mat'l. Report

AUG 29 1934



19" dia 11" 8

● Curb Box

4" Main

Elev. of Main at tap 4 1/2'

Gate at ●

● Gate at

● Curb Box

OLD TAP SHUT OFF AT MAIN