

## LABOR AND MATERIALS

|    |                               |   |                                      |                |          |
|----|-------------------------------|---|--------------------------------------|----------------|----------|
| 1  | Copper<br>Lead                | } Connection  | 3/4                                  |                | \$ 1.35  |
| 1  | Curb                          | { Cock Valve<br>T. S. & V. }                                  | 3/4                                  | in.            | \$ 1.80  |
| 1  | Service Box<br>Old - returned | { Short 3 1/2 x 4 1/2<br>Long 4 1/2 x 5 1/2<br>Buffer Rdway } |                                      |                | \$ 1.82  |
| 15 | Ft.                           | 3/4 in.   | { Copper<br>Galv-iron<br>Cast-iron } | Pipe at<br>.18 | \$ 2.34  |
|    | Nipples                       | in. at  |                                      |                | \$       |
|    | Bushings                      | to in. at   |                                      |                | \$       |
|    | Red'g<br>Inc'g                | Couplings   | to in. at                            |                | \$       |
|    | Union                         | in. at  |                                      |                | \$       |
|    | Meter                         | in. at  |                                      |                | \$       |
| 2  | Lead Joints at                | Copper  | 3"                                   |                | \$ 30    |
|    | Leadite Joints at             |   |                                      |                | \$       |
|    | Hrs. Foreman at               |   |                                      |                | \$       |
| 3  | Hrs. Chauffeur at             | 28.74   |                                      |                | \$ 4.13  |
| 9  | Hrs. Tapper at                | 7   |                                      |                | \$ 6.18  |
| 10 | Hrs. Labor at                 | .60   |                                      |                | \$ 6.00  |
|    | Hrs. Labor at                 |   |                                      |                | \$       |
|    | Hrs. Compressor at            |   |                                      |                | \$       |
|    | Compensation Ins.             |   |                                      |                | \$ 39    |
|    | Trucking                      |   |                                      |                | \$ 1.50  |
|    | Builders Use of Water         |   |                                      |                | \$ 3.85  |
|    | Tap Miller                    |   |                                      |                | \$       |
|    | Old tap dug up at main        |   |                                      |                | \$       |
|    | To be paid for                |   |                                      |                | \$       |
|    |                               |   |                                      |                | \$       |
|    |                               |   |                                      |                | \$       |
|    | <u>This Tap changed</u>       |   |                                      |                | \$ 31.14 |
|    | <u>from Tubaloy to Copper</u> |   |                                      |                |          |
|    | 1967.                         |   |                                      |                |          |

11743

St.  
~~St.~~  
Ave. No. 8

Division

Name of Owner

Mulcahy

Labor and Mat'l. Report June 23 1943



Main Elev. of Main at tap 6

Gate at ● ● Gate at

● Curb Box

Old Top Dug up at main to be paid for