

LABOR AND MATERIALS

1	Copper Lead	} Connection $\frac{3}{4}$	\$
1	Curb		} Cock Valve T.S. & V. } $\frac{3}{4}$ in.
1	Service box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ }	
31	Ft. $\frac{3}{4}$ in.		{ Copper C.I. C.I. } Pipe at
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g	} Coupl'gs to in. at	\$
	Union		in. at
	Meter	in. at	\$
			\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man—1	at	\$
	Hrs. Water Maint. Man—2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor—	at	\$
	Hrs. Compressor at		\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$

~~St~~
~~St~~
Ave. No. 10

DIX
Name of Owner
J. T. DOLAN

Labor and Mat'l. Report SEPT. 3 1935



35'3" 40'3"

● Curb Box

4" Main Elev. of Main at tap 4'

Gate at ● ● Gate at

TAX ID # 303.13-8-43

● Curb Box

OLD SHUT OFF AT MAIN