

LABOR AND MATERIALS

Copper	} Connection			\$	
Lead	} Cock Valve T. S. & V.	} in.			\$
Curb					
Service box	} Short 3½ x 4½ Long 4½ x 5½ Buff or Rdway	}			\$
Old returned					
6 Ft. 3/4 in.	} Copper C.I. C.I.	} Pipe at			\$
Nipples	in. at				\$
Bushings	to in. at				\$
Red'g	} Coupl'gs	} to in. at			\$
Inc'g					
Union	in. at				\$
Meter	in. at				\$
Lead Joints	at				\$
Compound Joints	at				\$
Maintenance Foreman					\$
Hrs. Water Maint. Man	1 at				\$
Hrs. Water Maint. Man	2 at				\$
Hrs. Garage Foreman	at				\$
Hrs. Labor	at				\$
Hrs. Compressor	at				\$
Compensation Ins.	at \$	per C			\$
Trucking					\$
Pav't Patch					\$
					\$
					\$
					\$
O'head					\$

~~St.~~ 137
~~Pt.~~ 47
 Ave. No. 47

Dix

Name of Owner
CHARLES I ZEROWITZ

Labor and Mat'l. Report 1980

CAR
WASH

19' 3"

● Curb Box

0 - 26' 9"

Main Elev. of Main at tap

Gate at ● ● Gate at

● Curb Box

LSM-5C-6-1-67