

LABOR AND MATERIALS

1	Copper } Connection	3/4			\$ 179	
	Lead					
1	Curb { Clock Valve	3/4 in.			\$ 261	
	T.S. & V.					
1	Service box	} Short 3/4 X 4 1/2			\$ 1.87	
	Old returned					Long 4 1/2 X 5 1/2
						Buff for Rdway
36 Ft.	3/4 in.	Copper } Pipe at 23			\$ 8.28	
		Galv. Iron				
		Cast Iron				
	Nipples	in. at			\$	
	Bushings	to in. at			\$	
	Red'g Inc'g	} Couplings	to in. at		\$	
	Union	in. at			\$	
	Meter	in. at			\$	
	Lead Joints	at			\$	
	Compound Joints	at			\$	
14	Hrs. Foreman at	Walm - 84			\$ 1176	
23	Hrs. Chauffeur at	75			\$ 1725	
3	Hrs. Tapper at	75			\$ 225	
23	Hrs. Labor at	65			\$ 1495	
	Hrs. Labor at				\$	
7	Hrs. Compressor at	87 1/2			\$ 613	
	Compensation Ins.				\$ 1.27	
	Trucking	3 days			\$	
	Builders Use of Water				\$	
	9 sticks clymanite				\$	
	18 caps				\$	
	Tap by Walsmsted				\$	
					\$	

6-46

-St.
 Pl.
 Ave. No. 166

Dix Ave

Name of Owner
 Overlook Works

Labor and Mat'l. Report Mar 26 1946

White Birch tree

10'10"

Curb Box

52'10"

N.Y.P. Part # 32

12" Main Elev. of Main at tap 6

Gate at ● ● Gate at

Curb Box

57' 809

LSM-SC-6-1-45

LABOR AND MATERIALS

_____	Copper	Connection	_____	\$	_____
_____	Lead				
_____	Curb	Cock Valve T.S. & V. } _____ in.		\$	_____
_____	Service box	{ Short 3-1/2 x 4-1/2		\$	_____
_____	Old returned	{ Long 4-1/2 x 5-1/2		\$	_____
SI _____	Ft. 7 in.	{ Copper G.I. C.I. } Pipe at	_____	\$	_____
_____	Nipples	_____ in. at	_____	\$	_____
_____	Bushings	_____ to _____ in. at	_____	\$	_____
_____	Red'g				
_____	Inc'g				
_____	Union	_____ in. at	_____	\$	_____
_____	Meter	_____ in. at	_____	\$	_____
_____				\$	_____
_____	Compound Joints at	_____		\$	_____
_____	Maintenance Foreman	_____		\$	_____
_____	Hrs. Water Maint. Man - 1 at	_____		\$	_____
_____	Hrs. Water Maint. Man - 2 at	_____		\$	_____
_____	Hrs. Garage Foreman	_____ at	_____	\$	_____
_____	Hrs. Labor	_____ at	_____	\$	_____
_____	Hrs. Compressor at	_____		\$	_____
_____				\$	_____
_____	Trucking			\$	_____
_____	Pav't Patch			\$	_____
_____				\$	_____
_____				\$	_____
_____				\$	_____
_____				\$	_____
_____				\$	_____

166 DIX St. Ave. No. 166
 Name of Owner _____

Labor and Mat'l. Report 19 6/9/07

● Curb Box

12 Main Elev. of Main at tap 6'

Gate at ● Gate at ●

● Curb Box

38' has coupling
 PIECED IN IT