



LABOR AND MATERIALS

Copper	} Connection		\$	
Lead				
Curb	} Cock Valve T. S. & V. }	in.	\$	
Service box		} Short 3½ x 4½ Long 4½ x 5½ }		
Old returned				\$
37 Ft. <sup>1</sup> / <sub>4</sub> in.	} Copper C.I. C.I.	Pipe at	\$	
Nipples		in. at	\$	
Bushings	to in. at	\$		
Red'g } Inc'g }	} Coupl'gs	to in. at	\$	
Union		in. at	\$	
Meter	in. at	\$		
		\$		
Compound Joints	at	\$		
Maintenance Foreman		\$		
Hrs. Water Maint. Man—1	at	\$		
Hrs. Water Maint. Man—2	at	\$		
Hrs. Garage Foreman	at	\$		
Hrs. Labor—	at	\$		
Hrs. Compressor	at	\$		
		\$		
Trucking		\$		
Pav't Patch		\$		
		\$		
		\$		
		\$		
		\$		
		\$		

DIX Ave. No. 168

Name of Owner  
OUDEKERK

Labor and Mat'l. Report FEB 1948



67'6" 50'0"

● Curb Box

12" Main Elev. of Main at tap

Gate at ● ● Gate at

● Curb Box