

LABOR AND MATERIALS

Copper	} Connection	_____	\$				
Lead		_____	\$				
Curb	} Cock Valve T. S. & V.	} _____ in.	\$				
				Service box	} Short 3½ x 4½	} _____	\$
Ft. _____ in.	} Copper G. I. C. I.	} Pipe at _____	\$				
Nipples _____ in. at _____				\$			
Bushings _____ to _____ in. at _____				\$			
Red'g } Inc'g }	} Coupl'gs _____ to _____ in. at _____	\$					
Union _____ in. at _____			\$				
Meter _____ in. at _____	\$						
_____	\$						
Compound Joints at _____	\$						
Maintenance Foreman _____	\$						
Hrs. Water Maint. Man—1 at _____	\$						
Hrs. Water Maint. Man—2 at _____	\$						
Hrs. Garage Foreman _____ at _____	\$						
Hrs. Labor _____ at _____	\$						
Hrs. Compressor at _____	\$						
_____	\$						
Trucking _____	\$						
Pav't Patch _____	\$						
_____	\$						
_____	\$						
_____	\$						
_____	\$						
_____	\$						

DIX

Ave. No. 178

Name of Owner


FORMERLY WAGGAMAN & COLLYER

Labor and Mat'l. Report

NOV 10 1931

STOREHOUSE + GARAGE 15'

62'-7" 50'

STONE PILLAR
● Curb Box 5'-6" 

12" Main

Elev. of Main at tap _____

Gate at ●

● Gate at

● Curb Box